



In the event of a conflict in member sizes shown on the plans and the general notes, the contractor must utilize the more stringent member size requirements.

Engineer: Michael Thompson, P.E. 47509/CA30930